## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT •
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



Application No.: 10/698,968
Title: Multi-Domain Vertical Alignment LCD...

Inventor: Hiap L. Ong
Replacement Sheet

1/6



**/**10 32 -24 -30 36 36 36 -26 -34 -34 -20 -22

**PRIOR ART** FIG. 1B

20

\ 28

20

28

Application No.: 10/698,968
Title: Multi-Domain Vertical Alignment LCD...

Inventor: Hiap L. Ong
Replacement Sheet




FIG. 2A




FIG. 6

Application No.: 10/698,968
Title: Multi-Domain Vertical Alignment LCD...
Inventor: Hiap L. Ong

Replacement Sheet




FIG. 2B




FIG. 2C

Application No.: 10/698,968
Title: Multi-Domain Vertical Alignment LCD...

Inventor: Hiap L. Ong

Replacement Sheet

4/6

300




FIG. 3

Application No.: 10/698,968
Title: Multi-Domain Vertical Alignment LCD...
Inventor: Hiap L. Ong
Replacement Sheet




FIG. 4




FIG. 5

Application No.: 10/698,968

Title: Multi-Domain Vertical Alignment LCD...

Inventor: Hiap L. Ong

Replacement Sheet

